

# Technical Service Bulletin

Subject: Electrical Cabrio Top Wiring Harness    Models: 911 Cabrio 1986

Bulletin Number: 86 – 06

The harness routing and fastening below the right gear system (A) was improved in production as of June 1986.

In case of wiring interference with the gear linkage on older cars, the 12 pin plug should be relocated to the angled sheet metal bracket.

(B on sketch)

