

## Bosch 0231.169.001 Advance Curve

Dist RPM	Low Side Adv	High Side Adv	Actual Advance
0	-1	1	0
250	-1	1	0
550	-1	1	0
700	-1	4	0
1000	5	8	6
1250	6	9	7
1500	7	10	8
1750	8	11	9
2000	9	12	10
2250	10	13	11
2500	11	14	12
2750	12	15	13
3000	13	16	14
3250	13	16	14
3500	13	16	14
3750	13	16	14
4000	13	16	14

Note Rpm and Advance Degrees are in Distributor Advance to get engine Advance Double the values

### Dwell

38°

### Vacuum Retard Operation

mBar Vacuum	Retard In Distributor Degrees
25	0
50	0
75	1
100	2
125	3
150	4
175	5
200	5
225	5
250	5
275	5
300	5

