

Bosch 0231.169.005 Advance Curve

Dist RPM	Low Side Adv	High Side Adv	Actual Advance
0	-1	1	0
250	-1	1	0
550	-1	1	0
750	-1	4	0
1000	4	8	5
1250	5	9	7
1500	6	10	8
1750	7	11	9
2000	8	12	10
2250	9	13	11
2500	10	14	12
2750	11	15	13
3000	12	16	14
3250	12	16	14
3500	12	16	14
3750	12	16	14
4000	12	16	14

Note Rpm and Advance Degrees are in Distributor Advance to get engine Advance Double the values

Dwell
39°

Vacuum Retard Operation

mBar Vacuum	Retard In Distributor Degrees
25	0
50	0
75	1
100	2
125	3
150	4
175	5
200	6
225	6
250	6
275	6
300	6

