

Bosch 0231.184.001 Advance Curve

Dist RPM	Low Side Adv	High Side Adv	Actual Advance
0	-1	1	0
250	-1	1	0
550	-1	1	0
700	-1	4	2
1000	5	8	7
1250	7	9	8
1500	8	10	9
1750	9	11	10
2000	10	12	11
2250	11	13	12
2500	12	14	13
2750	13	15	14
3000	13	16	15
3250	13	16	15
3500	13	16	15
3750	13	16	15
4000	13	16	15

Note Rpm and Advance Degrees are in Distributor Advance to get engine Advance Double the values

Dwell
38°

Vacuum Retard Operation

mBar Vacuum	Retard In Distributor Degrees
25	0
50	0
75	1
100	2
125	3
150	4
175	5
200	5
225	5
250	5
275	5
300	5

