

Bosch 0237.301.002 Advance Curve

Dist RPM	Low Side Adv	High Side Adv	Actual Advance
0	-1	1	0
250	-1	1	0
550	-1	1	0
700	-1	1.75	0
1000	1	3.25	2
1250	2.75	4.75	3
1500	4	6	4.5
1750	5.2	7	5.5
2000	5	6.75	6
2250	4.75	6.5	6
2500	4.5	6.25	5.75
2750	4.25	6	5.5
3000	4	5.75	5.25
3250	3.75	5.5	5
3500	3.5	5.25	4.75
3750	3.25	5	4.5
4000	3	4.75	4.25

Note Rpm and Advance Degrees are in Distributor Advance to get engine Advance Double the values

Dwell

N/A Impulse Trigger

Vacuum Retard Operation

mBar Vacuum	Retard In Distributor Degrees
25	0
50	0
75	1
100	3
125	5
150	7
175	8
200	8
225	8
250	8
275	8
300	8

