



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

swap meet sales
United States

Quotation # S00053

Quotation Date	Expiration	Salesperson
02/06/2025	02/21/2025	Kurt Donohoe

DESCRIPTION	QUANTITY	UNIT PRICE	TAXES	AMOUNT
<i>1969 911T Engine 6196078</i>				
Engine Machine Work				
[Crankcase Close and Hone Sublet] Close and Hone Crankcase Back To Standard. Includes machining cylinder deck surfaces	1.0000 Units	1,445.0000		\$ 1,445.00
[Oil By-Pass Modification] Oil System By-Pass Modification. Updates Oil by-pass system to circulate oil blow off.	1.0000 Hours	192.8500		\$ 192.85
Cylinder Head Service Disassemble and clean cylinder heads (6), Bead Blast and inspect. Cut precision 3 angle valve seat, Grind valves if applicable. Re-assemble cylinder heads and set valve and spring installed heights. Pressure test heads for leakage	1.0000 Units	850.0000		\$ 850.00
Valve Guide Service Remove and Replace Valve Guides. Ream and hone valve guides to correct size and clearance.	12.0000 Units	25.0000		\$ 300.00



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

Valve Seat Service Remove and install new valve seats	12.0000 Units	65.0000	\$ 780.00
Cam Tower Service Service Cam Towers (1 Pair), Vapor blast and tumble, Remove end plugs and clean Spray bar, Custom Machine new end plugs, and install, Measure, and polish cam journals	1.0000 Units	385.0000	\$ 385.00
Machine Cylinder Heads Machine Cylinder head to barrel surfaces (6)	1.0000 Units	400.0000	\$ 400.00
Time-sert Head stud Drill cylinder head stud threads to first over-size, tap and install deep Time-Sert insert. (24) (Price does not include the inserts)	1.0000 Units	560.0000	\$ 560.00
Crank Polish Micro Polish Crankshaft	1.0000 Units	75.0000	\$ 75.00
Connecting Rod Service Connecting Rod Service, Clean and media polish Rod. Remove and replace Rod bolts and nuts, Clean inspect and hone or replace rod bushing. (Per Rod, price does not include bushing if required)	6.0000 Units	45.0000	\$ 270.00
Hot Tank	1.0000 Hours	65.0000	\$ 65.00
Intake Manifold Service Disassemble all studs from the intake manifold set. Media blast intake manifolds. Machine both gasket surfaces. Ceramic coat and bake intake manifold set after work has been completed	1.0000 Units	475.0000	\$ 475.00



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

Subtotal \$ 5,797.85

Labor				
911 Engine Rebuild	1.0000 Units	6,000.0000		\$ 6,000.00
R Engine Rebuild				
Rebuild the complete 911 Engine. This includes removing and installing the intake and exhaust system and setting it to the side. Completely disassemble the engine and wash the components. Measure and inspect all engine parts. Replace all necessary parts and reassemble the engine, making all necessary adjustments and settings. Reinstall intake and exhaust systems.				
Rebuild ignition Distributor	1.0000 Units	475.0000		\$ 475.00
Re- finish fan shroud	2.5000 Units	150.0000		\$ 375.00
Sublet Work	1.0000 Hours	375.0000		\$ 375.00
Powder Coat Engine Tin				
Rebuild timing chain tensioners	2.0000 Units	150.0000		\$ 300.00
Subtotal				\$ 7,525.00

Parts				
[901.100.902.01] Engine Gasket Set	1.0000 Units	333.0000	Out	\$ 333.00
Carburetor engines 2.0/2.2L			of	
			State	



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

911.101.901.00 Std main bearing set	1.0000 Units	269.6300	Out of State	\$ 269.63
[901.101.138.03] Std Nose Bearing, (Number 8) Std Nose Bearing, (Number 8)	1.0000 Units	267.4700	Out of State	\$ 267.47
[901.103.141.00] Std Rod Bearing Set, 1965-1971 Model 911 2.0L and 2.2L Engines	1.0000 Units	81.6000	Out of State	\$ 81.60
[930.104.321.50] Std Valve Guide, .514" OD .315" (8mm)ID , Will fit intake and exhaust Valves on all Porsche 911 models	12.0000 Units	9.9700	Out of State	\$ 119.64
[901.105.408.50] 38 mm Exhaust Valve, Will fit Porsche 1969-71 model 2.0L and 2.2L Engines in the 911T and 914/6	6.0000 Units	47.6000	Out of State	\$ 285.60
993.105.529.00 Timing Chain Without link	2.0000 Units	149.3300	Out of State	\$ 298.66
911.105.222.05 Brown timing Chain Guide	1.0000 Units	12.4300	Out of State	\$ 12.43
[699.1126] M10 X1.5 x 24.5mm Time Sert Insert M10 X1.5 x 24.5mm Time Sert Insert	24.0000 Units	5.0000	Out of State	\$ 120.00



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

911.105.222.07 Black Timing Chain Guide Rail	5.0000 Units	10.4200	Out of State	\$ 52.10
[911.101.172.00] Cylinder Head Stud Cylinder Head Stud	24.0000 Units	24.5600	Out of State	\$ 589.44
[901.103.909.JE] 911T Forged JE Piston and Liner Set, 9.5:1 Compression, 81mm Bore Size 911T Forged JE Piston and Liner Set, 9.5:1 Compression, 81mm Bore Size	1.0000 Units	1,927.8000	Out of State	\$ 1,927.80
Sublet Plating Replate Parts As Required	1.0000 Units	275.0000		\$ 275.00
Engine hardware kit. Includes all new nylock nuts, Tin wear bolts and washers, and other hardware required at engine assembly	1.0000 Units	175.8900	Out of State	\$ 175.89
[901.106.085.05] Rear Engine Tin. 1965-83 911 Models For cars without air injection	1.0000 Units	275.0000	Out of State	\$ 275.00
[999.170.010.91] W4CS Spark Plug, Used in the Porsche 1965-71 Model 911 and 911T's	6.0000 Units	28.6500	Out of State	\$ 171.90
[911.609.061.00] Ignition Wire Set, 1965-77 911T, E, and S Models Ignition Wire Set, 1965-77 911T, E, and S Models	1.0000 Units	155.5500	Out of State	\$ 155.55



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

[911.111.025.05] OEM Stock Replacement Dansk Muffler OEM Stock Replacement Dansk Muffler	1.0000 Units	678.3000	Out of State	\$ 678.30
[911.211.021.60] Left Side Dansk Heat Exchanger factory original finish '65-'77 Left Side Dansk Heat Exchanger factory original finish '65-'77	1.0000 Units	814.3000	Out of State	\$ 814.30
[911.211.022.10] Right Side Dansk Heat Exchanger, Factory finish '65-'77 Right Side Dansk Heat Exchanger, Factory finish '65-'77	1.0000 Units	967.3000	Out of State	\$ 967.30
[901.107.041.03] Engine oil cooler 65-71 Engine oil cooler 65-71	1.0000 Units	1,738.7400	Out of State	\$ 1,738.74
[901.108.131.00] Phenolic Intake Manifold Insulator, 1969-73 Model 911T Phenolic Intake Manifold Insulator, 1969-73 Model 911T	6.0000 Units	13.8900	Out of State	\$ 83.34
[996.101.137.80] Intermediate bearing set, Thrust	1.0000 Units	28.0000	Out of State	\$ 28.00
[996.101.435.71] Intermediate shaft bearing set	1.0000 Units	27.3530	Out of State	\$ 27.35
[999.192.176.50] Alternator Belt 1965-77 911 models Alternator Belt 1965-77 911 models	1.0000 Units	12.2030	Out of State	\$ 12.20



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

[901.107.347.01] Oil Line '65-83 911, '70-72 914, '78-79 930	1.0000 Units	49.3000	Out of State	\$ 49.30
[901.107.348.00] Right Side Oil Feed Line, Non Pressure Fed Tennsioners	1.0000 Units	44.2000	Out of State	\$ 44.20
[901.006.509.00] Ignition Timing Decal, 911T 1965-72 Models	1.0000 Units	33.6400	Out of State	\$ 33.64
[911.104.315.50] 35 mm Exhaust Valve Seat, Oversize, See Drawing for Detailed sizes	6.0000 Units	12.6990	Out of State	\$ 76.19
[901.111.157.04] Rear Muffler Strap Rear Muffler Strap	2.0000 Units	20.2130	Out of State	\$ 40.43
[911.603.120.06] New Internally Regulated Alternator,Fits 911 models 1965-75 Replaces the Externally regulated alternator	1.0000 Units	347.9560	Out of State	\$ 347.96
[901.211.194.01.U] Hot air hose Brown Hot air hose Brown	2.0000 Units	13.6000	Out of State	\$ 27.20
[901.741.551.01] Oil Pressure Sending Unit Oil Pressure Sending Unit	1.0000 Units	48.9800	Out of State	\$ 48.98



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

Oil Pressure control update kit. Includes spring, guide rod, piston, and new plug	1.0000 Units	69.9900	Out of State	\$ 69.99
[901.107.331.12] Oil Line, Engine Return To Oil Tank, 911 1965-71 models Oil Line, Engine Return To Oil Tank, 911 1965-71 models	1.0000 Units	96.7300	Out of State	\$ 96.73
[901.609.591.00] 6 Cylinder Ignition Wire Holders 6 Cylinder Ignition Wire Holders	4.0000 Units	6.9100	Out of State	\$ 27.64
[901.108.955.11] Air Filter, 1965-73 911 Models MFI and Carburetored	1.0000 Units	24.6670	Out of State	\$ 24.67
[901.108.019.00] Air Cleaner Snorkel, Used	1.0000 Units	375.0000	Out of State	\$ 375.00
Alternator Wiring harness	1.0000 Units	118.4300	Out of State	\$ 118.43
Subtotal				\$ 11,140.60

Carburetors



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

Weber IDA Service	1.0000 Units	1,975.0000		\$ 1,975.00
Weber Carburetor Repair Service. Disassemble the complete carburetor set, clean it, and inspect it for wear. Remove all studs and send out to be re-plated. Machine Labor Gasket surfaces as required. Remove carburetor lead plugs and flush fuel passageways.				
[901.100.811.00] Float Pivot IDA Float Pivot Arm	2.0000 Units	12.2000	Out of State	\$ 24.40
[41015.007] IDA Float	4.0000 Units	44.9700	Out of State	\$ 179.88
[79701.000] 40 IDA 3 BBL Inlet exhaust valve Used to adjust the fuel delivery on the Weber IDA 3 barrel Carburetor	2.0000 Units	18.0000	Out of State	\$ 36.00
[77201.18] IDA Air Corrector 180	6.0000 Units	11.2700	Out of State	\$ 67.62
[73801.125] IDA Main Jet .125	6.0000 Units	9.8700	Out of State	\$ 59.22
[74403.05] IDA Idle Jet,.050	6.0000 Units	10.2300	Out of State	\$ 61.38



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

[64750.002] IDA Air By Pass Screw Air Bypass Screw, Used to adjust air flow on Weber Carburetors	6.0000 Units	9.6000	Out of State	\$ 57.60
[901.100.979.00] IDA Main jet Holder	6.0000 Units	9.0000	Out of State	\$ 54.00
[64750.003] IDA Mixture Screw	6.0000 Units	8.8500	Out of State	\$ 53.10
[901.100.944.00] IDA Pump Spring	2.0000 Units	4.5000	Out of State	\$ 9.00
[901.108.631.00] IDA Throttle Return Spring	2.0000 Units	6.7800	Out of State	\$ 13.56
[901.100.941.98] IDA Throttle shaft kit Weber IDA Throttle Shaft set Standard size	1.0000 Units	96.2400	Out of State	\$ 96.24
[64005.126] Std Throttle Plate Weber IDA Std Throttle Plate Weber IDA	6.0000 Units	6.9900	Out of State	\$ 41.94
[32486.001] Weber IDA Pump Lever Pivot Pin Weber IDA Pump Lever Pivot Pin	2.0000 Units	6.4600	Out of State	\$ 12.92



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

[901.100.973.00] IDA Progression hole plug	6.0000 Units	8.4200	Out of State	\$ 50.52
[901.100.955.01] IDA Throttle shaft Coupling Aftermarket Weber 40 and 46m/m 3 Barrel Carburetors, Throttle Shaft Coupling	2.0000 Units	9.4300	Out of State	\$ 18.86
[901.100.801.00] Needle and Seat Plug Plug, For Needle and Seat IDA Carburetors	4.0000 Units	12.8400	Out of State	\$ 51.36
[58000.006] Oring Cup Weber Carburetors	6.0000 Units	1.1800	Out of State	\$ 7.08
[Weber 40 IDA Service Kit] Weber 40 IDA 3BBL Service kit with pump diaphragms and needle/seats.	2.0000 Units	84.2100	Out of State	\$ 168.42
Cerakote Carburetors Cerrakote Finish Carburetors in either a colored or clear finish	1.0000 Units	375.0000		\$ 375.00
Cerakote supplies Cerakote Supplies used to refinish carburetor bodies and components	1.0000 Units	65.0000	Out of State	\$ 65.00
[901.100.806.00] Bowl Plug Weber IDA	4.0000 Units	12.8600	Out of State	\$ 51.44



KNSD.LLC
6500 W Snowbowl View Cir
Flagstaff AZ 86001
United States

[901.100.983.01] 40/30 Choke Weber IDA 3 Series Choke, 30mm, 911L Models 71502.300	6.0000 Units	28.5200	Out of State	\$ 171.12
[61287.001] IDA Adjustable Pump Rod IDA Weber Pump Rod	2.0000 Units	33.9800	Out of State	\$ 67.96
Subtotal				\$ 3,768.62

Untaxed Amount	\$ 28,232.07
Out of state on \$ 12,284.22	\$ 0.00
Total	\$ 28,232.07